



- |   |  |   |  |   |
|---|--|---|--|---|
| <p><b>(D)</b></p> <ul style="list-style-type: none"> <li>• Sicherungseinsätze und Trennmesser mit versilberten Oberflächen einsetzen.</li> <li>• Zügig schalten.</li> </ul> | <p><b>(GB)</b></p> <ul style="list-style-type: none"> <li>• Use silver-coated fuse-links and solid-links.</li> <li>• Operate quickly.</li> </ul> | <p><b>(PL)</b></p> <ul style="list-style-type: none"> <li>• Wkładki bezpiecznikowe oraz zwieracze nożowe stosuj wyłącznie srebrzone.</li> <li>• Łączyć szybko.</li> </ul> | <p><b>(ES)</b></p> <ul style="list-style-type: none"> <li>• Utilizar fusibles y cuchillas seccionadoras con contactos de plata.</li> <li>• Rapida maniobra.</li> </ul> | <p><b>(RU)</b></p> <ul style="list-style-type: none"> <li>• применять предохранители и разъединительные ножи только с посеребрёнными контактами</li> <li>• включать и разъединять быстро</li> </ul> |
|---|--|---|--|---|

EN/IEC60947-3  
VDE 0660 T107







