



- | | | | | |
|---|--|---|--|---|
| <p>(D)</p> <ul style="list-style-type: none"> • Sicherungseinsätze und Trennmesser mit versilberten Oberflächen einsetzen. • Zügig schalten. | <p>(GB)</p> <ul style="list-style-type: none"> • Use silver-coated fuse-links and solid-links. • Operate quickly. | <p>(PL)</p> <ul style="list-style-type: none"> • Wkładki bezpiecznikowe oraz zwieracze nożowe stosuj wyłącznie srebrzone. • Łączyć szybko. | <p>(ES)</p> <ul style="list-style-type: none"> • Utilizar fusibles y cuchillas seccionadoras con contactos de plata. • Rapida maniobra. | <p>(RU)</p> <ul style="list-style-type: none"> • применять предохранители и разъединительные ножи только с посеребрёнными контактами • включать и разъединять быстро |
|---|--|---|--|---|

EN/IEC60947-3
VDE 0660 T107







